



## LuK Service Info



**Part Nr: 133 0608 10 — 330mm DBFR**

**Part Nr: 133 0271 10 — 330mm TBFR**

Manufacturer: NEW HOLLAND FORD

Model: 3000, 4000, 5000, Series & Industrial

Art.-Nr.: **133 0608 10 / 133 0271 10**

Info: 133 0608 10 replaces/ersetzt/remplace/  
sustituye a/sostituisce 130 0018 10 133  
0271 10 replaces/ersetzt/remplace/  
sustituye a/sostituisce 133 0017 10

### FOR NON SYNCHRONIZED TRANSMISSION

 When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.

 Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.

 Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.

 Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.

 Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.



Call : +44 (0) 1432 264264  
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER  
**REP>XPERT**