



# Intake manifold module PTA519-0129

Technical note on special equipment codes:

## Attention!

Before installing the intake manifold module, check the special equipment codes (SA codes from Mercedes-Benz) and compare them with the vehicle data.

This intake manifold module is not compatible with SA codes 460, 494, 637K, 929K, 937K, 940K.

Possible consequences of not following these instructions:

- Error memory entry in the engine control unit.
- Engine warning light is illuminated.
- Basic settings/parameter adaptation to the engine control unit not possible.



**In the case of a warranty claim, proof of characteristic value adaptation and an error memory log must be attached.**